

**Flood Control Project Maintenance
Levee Inspections
2008 Channel Summary Report
Overall Unit and Item Ratings**

Fairfield Suisun Sewer District

Laurel Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling	A
	Encroachments	A
	Rip Rap Revetments	A
	Erosion	A

McCoy Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling	A
	Encroachments	A
	Rip Rap Revetments	A
	Erosion	A

Union Avenue Diversion

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling	A
	Encroachments	A
	Rip Rap Revetments	A
	Erosion	A

Flood Control Project Maintenance

Unit Cover Sheet

2008 Channel Inspection Results

Fairfield Suisun Sewer District

Channel
Laurel Creek

Date of Inspection	11/4/2008
DWR Inspector	John Williamson
Channel Rating	A

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
Laurel Creek	11/04/2008	John Williamson

Rpt Line	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A	vegetation growth cat tails, bull rushes some saplings in channel will not impede flow but should be controled with herbicides or manual removal,have cleared 50' upstreamed and downstream of crossings	°	Y	1
2	Rivers, Channels & Designated Floodways	Shoaling		A		°		4
3	Rivers, Channels & Designated Floodways	Encroachments		A		°		2
4	Rivers, Channels & Designated Floodways	Rip Rap Revetments		A		°		3
5	Rivers, Channels & Designated Floodways	Erosion		A		°		5

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
Laurel Creek	11/04/2008	John Williamson

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Upstream at Cement Hill Road looking towards Gulf Avenue and intersection of Union Ave. Diversion	



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Downstream at Cement Hill Road	



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Upstream at Meadowlark Drive	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected	C : Corrected
--	--	--	---------------

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
Laurel Creek	11/04/2008	John Williamson

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream at Meadowlark Drive



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream at Matthew Road



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream at Matthew Road looking towards railroad culvert under crossing



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected	C : Corrected
--	--	--	---------------

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
Laurel Creek	11/04/2008	John Williamson

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream at Worley Road



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

downstream Worley Road



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

reinspection 11-04-2008 Worley Road upstream



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected	C : Corrected
--	--	--	---------------

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
Laurel Creek	11/04/2008	John Williamson

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

clearing downstream Worley Road



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

upstream Blossom Drive removal



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Blossom Drive removal downstream



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected	C : Corrected
--	--	--	---------------

Flood Control Project Maintenance

Unit Cover Sheet

2008 Channel Inspection Results

Fairfield Suisun Sewer District

Channel
McCoy Creek

Date of Inspection	11/4/2008
DWR Inspector	John Williamson
Channel Rating	A

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
McCoy Creek	11/04/2008	John Williamson

Rpt Line	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A	vegetation growth cat tails, bull rushes and saplings should not impede flow and should be controlled by herbicide or manual removal, have cleared crossings 50' feet upstream and downstream, reinspection 11-04-2008	°	Y	1
2	Rivers, Channels & Designated Floodways	Shoaling		A		°		4
3	Rivers, Channels & Designated Floodways	Encroachments		A		°		2
4	Rivers, Channels & Designated Floodways	Rip Rap Revetments		A		°		3
5	Rivers, Channels & Designated Floodways	Erosion		A		°		5

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
McCoy Creek	11/04/2008	John Williamson

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream Bella Vista Drive



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Control structure overgrown with tullies at Bella Vista Drive



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Down stream at Bella Vista Drive



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected	C : Corrected
--	--	--	---------------

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
McCoy Creek	11/04/2008	John Williamson

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream at Emperor Drive



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream at Emperor Drive looking towards confluence of Laurel Creek



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream at Pintail Drive looking towards the confluence of Laurel Creek



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
McCoy Creek	11/04/2008	John Williamson

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream at Pintail Avenue



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream at Anderson Drive



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream at Anderson Drive looking towards Suisun Bay



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected	C : Corrected
--	--	--	---------------

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
McCoy Creek	11/04/2008	John Williamson

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
reinspection 11-04-2008 upstream removal of cattails at Emperor Drive	



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Downstream removal of cattails at Emperor Drive	



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions
Pintail Drive reinspection 11-04-2008 removal of debris, cattails and clearing bays under bridge downstream	



* Location LS : Land Side WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected	C : Corrected
--	--	--	--	--	---------------

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
McCoy Creek	11/04/2008	John Williamson

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Pintail Drive upstream removal of cattails



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

reinspection 11-04-2008 upstream at Hiway 12
removal of vegetation



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected	C : Corrected
--	--	--	---------------

Flood Control Project Maintenance

Unit Cover Sheet

2008 Channel Inspection Results

Fairfield Suisun Sewer District

Channel
Union Avenue Diversion

Date of Inspection	11/4/2008
DWR Inspector	John Williamson
Channel Rating	A

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
Union Avenue Diversion	11/04/2008	John Williamson

Rpt Line	Category	Item	Location *	Rating **	Comment	GPS	Photo	Issue
1	Rivers, Channels & Designated Floodways	Vegetation & Obstructions		A			° °	Y 1
2	Rivers, Channels & Designated Floodways	Shoaling		A			° °	4
3	Rivers, Channels & Designated Floodways	Encroachments		A			° °	2
4	Rivers, Channels & Designated Floodways	Rip Rap Revetments		A			° °	3
5	Rivers, Channels & Designated Floodways	Erosion		A			° °	5

* Location

LS : Land Side
WS : Water Side
CR : Crown

** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
Union Avenue Diversion	11/04/2008	John Williamson

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from Camrose Avenue



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream from Camrose Avenue towards N. Texas St.



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Start of Diversion channel downstream at North Texas Street



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected	C : Corrected
--	--	--	---------------

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
Union Avenue Diversion	11/04/2008	John Williamson

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream from Dover Avenue



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream from Dover Avenue



Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Downstream at Gulf Drive looking towards intersection of Loral Creek



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected	C : Corrected
--	--	--	---------------

Flood Control Project Maintenance

Inspection Report - Channel 2008

Fairfield Suisun Sewer District

Channel	Inspection Date	Inspector
Union Avenue Diversion	11/04/2008	John Williamson

Report Line	1
Location	
Category	Rivers, Channels & Designated Floodways
Item	Vegetation & Obstructions

Upstream at Gulf Drive looking towards Dover Ave.



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected
--	---